DEPARTMENT OF THE NAVY
NAVAL SEA SYSTEMS COMMAND DETACHMENT
RADIOLOGICAL AFFAIRS SUPPORT OFFICE (RASO)
NWS P.O. DRAWER 260
YORKTOWN, VA 23691-0260

ENTER INTO DATABASE ____
FILE: LICENSE: ____
PERMIT: ✓
YEARLY: ____
COPY TO PDR
OTHER ____

5104/00024
Ser 02B/991537/0776
23 November 1999

From: Officer in Charge, Naval Sea Systems Command Detachment, Radiological Affairs Support Office (RASO)
To: Commander, Naval Sea Systems Command (SEA 04LR)

Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTION OF NAVAL SEA SYSTEMS COMMAND DURING THE PERIOD 21 JUNE 1999 TO 3 AUGUST 1999

Ref: (a) CNO ltr 5104 Ser N455/9U595880 of 19 Sep 99
(b) NAVSEASYSCOM ltr 9492 Ser 04RLB/128 of 7 Oct 99

1. Reference (a) reported deficiencies as a result of the subject inspection of radioactive commodities operations authorized by Naval Radioactive Materials Permit (NRMP) No. 45-00024-T1NP. Your response to these deficiencies, reference (b) has been reviewed.

2. Compliance with findings E.3, F.56, and J.5 has not yet been achieved. Per reference (a), progress reports are required every 30 days until all deficiencies are corrected and compliance is achieved.

3. NAVSEADET RASO point of contact is Mr. Timothy P. Hart or Mr. Richard W. Lowman at DSN 953-4692, commercial (757) 887-4692 or commercial fax (757) 887-3235.

S. W. Doremus
S. W. DOREMUS

Copy to:
CNO (N455)
COMNAVSEASYSCOM (SEA 04N)
NRC Region II

MC21