Union Electric
Callaway Plant

PO Box 620
Fulton, MO 65251

June 12, 2000

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001

ULNRC-04267

Gentlemen:

DOCKET NUMBER 50-483
UNION ELECTRIC CO.
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-30
MONTHLY OPERATING REPORT
MAY, 2000

The enclosed Monthly Operating Report for May, 2000 is submitted pursuant to Section 5.6.4 of the Callaway Unit 1 Technical Specifications.

Warren A. Witt for
R. D. Affolter
Manager, Callaway Plant

RDA/JER/slk

Enclosure

IE24

MRR-0103

cc: Mr. Ellis W. Merschoff
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Jack Donohew (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 7E1
Washington, DC 20555-2738

Manager, Electric Department
Missouri Public Service Commission
PO Box 360
Jefferson City, MO 65102

Mr. Thomas A. Baxter
Shaw, Pittman, Potts, & Trowbridge
2300 N. Street N.W.
Washington, DC 20037

Enclosure
ULNRC-04267
June 12, 2000

DOCKET NO.:	50-483
UNIT NAME:	CALLAWAY UNIT 1
COMPLETED BY:	J. E. Ready
TELEPHONE:	573/676-8617
FAX:	573/676-4202

REPORTING PERIOD: **MAY, 2000**

1. DESIGN ELECTRICAL RATING (MWe-Net): 1171
2. MAX. DEPEND. CAPACITY (MWe-Net): 1125

		THIS MONTH	YR TO DATE	CUMULATIVE
3.	NUMBER OF HOURS REACTOR WAS CRITICAL	744	3,631	121,234
4.	HOURS GENERATOR ON-LINE	744	3,625	119,512.7
5.	REACTOR RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
6.	NET ELECTRICAL ENERGY GENERATED (MWH)	842,609	4,136,504	130,918,055

Enclosure
ULNRC-04267
June 12, 2000

UNIT SHUTDOWNS

DOCKET NO.:	50-483
UNIT NAME:	CALLAWAY UNIT 1
COMPLETED BY:	J. E. Ready
TELEPHONE:	573/676-8617
FAX:	573/676-4202

REPORT MONTH: MAY, 2000

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON	METHOD OF SHUTTING DOWN THE REACTOR	CORRECTIVE ACTIONS/COMMENT

SUMMARY

The Callaway plant operated at approximately 100% power for the month of May with several 4% downpowers for PORV testing.

REASON	METHOD
A: EQUIPMENT FAILURE (EXPLAIN)	1: MANUAL
B: MAINT. OR TEST	2: MANUAL SCRAM
C: REFUELING	3: AUTOMATIC SCRAM
D: REGULATORY RESTRICTION	4. CONTINUATION
E: OPERATOR TRAINING / LICENSE EXAMINATION	5: OTHER (EXPLAIN)
F: ADMINISTRATIVE	
G: OPERATIONAL ERROR (EXPLAIN)	
H: OTHER (EXPLAIN)	