# SFP

2/4/00

CT:

→ Hubbard brought over revised pages.
He just missed one of our proposed changes.
Farouk will now forward the package through RES mgmt for concurrence.

→ cladding failure and
zirconium oxidation temperatures

565°C very conservative (10 hours)

MELCOR 900°C
MAAP 930°C

F119