Mike
Me

3/3/99

init event λ ↑
source term ↑↓
decay heat ↓
time to respond ↑
λ maint errors ↑
operator attention ↓
heavy loads ↑

corrosion poor maint.
ageing
no early fatalities w/o fire

B/92