Conf Call w/ R. Barrett in Maine 10/15/99

framework on best understanding of what drives human perf
so h.p. isn't a risk drivers

good awareness (procedures, turnovers)
meaningful instr, be vigilant, alarms, trends
maintain instr

given instr, need procedures.
indication of available offsite sources
training in procedures (more awareness)

Asked couple of things
a. right issues to look at
b guidance on error prob

Ans: pointed us to literature that said what perf
we needed to put into place.

B/207