6/16/99

J. Hannon
V. Ordaz
Me

Dick Dudley
George Hubbard

Pre-workshop Meeting

① What do we need to discuss at the Monday meeting?

A. Tell NEI/industry we only want to discuss fixes & our concerns

Me → B. Discuss what I did in performing the analysis.

We don't debate

i. assumptions

ii. human error analysis

iii. Walk through sequences

iv. What are our concerns driven by for each sequence

2 hrs incl. questions

C. Output of technical criteria to allay technical concerns w/in the context of 10CFR50.12

B/17/

Events - No longer visible