Heavy Loads

0612 gives 10^{3} benefit

10^{-7}

~~Small piece~~

$\bar{P}$ of crane failure & Dropped load

10% of crane failure

$5 \times 10^{-5} \times .1 = 5 \times 10^{-6}$

80 plants don't have Phase

75 no [illegible] crane

2×10^{-6}

112