10 CFR 2.790(d) INFORMATION

October 29, 2001

10 CFR 2.790(d) INFORMATION

Mr. John K. Wood
Vice President - Nuclear
FirstEnergy Nuclear Operating Company
P. O. Box 97, A200
Perry, OH 44081

SUBJECT: PERRY NUCLEAR POWER PLANT
NRC SECURITY INSPECTION REPORT 50-440/01-14(DRS)

Dear Mr. Wood:

On August 30, 2001, the NRC completed a routine baseline inspection at your Perry Nuclear Power Plant. The enclosed report presents the results of that inspection. The results of this inspection were discussed with Mr. K. Ostrowski, and other members of your staff on August 30, 2001.

The inspection was an examination of activities conducted under your license as they relate to the Safeguards Strategic Performance Area and compliance with the Commission's rules and regulations and with the conditions of your license. Within this area, the inspection consisted of a selected examination of procedures and representative records, observation of activities, and interviews with personnel. Specifically, this inspection focused on Access Control; Access Authorization; Security Plan Changes; and Security Performance Indicator Verification.

Based on the results of this inspection, no significant findings were identified. A licensee identified issue of very low safety significance (Green), and which constituted a Non-Cited Violation, was identified pertaining to the lack of required emergency power for the security system for a period of 21 days. The details of this issue are considered 10 CFR 2.790(d) Information and exempt from public disclosure.

The attachment to this letter contains 10 CFR 2.790(d) Information and must be protected in accordance with the provisions of 10 CFR 2.790(d).

ENCLOSURE CONTAINS 10 CFR 2.790 INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED

10 CFR 2.790(d) INFORMATION

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, excluding the enclosure, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/NRC/ADAMS/index.html (the Public Electronic Reading Room).

Sincerely,

/RA by James L. Belanger Acting for/

James R. Creed
Safeguards Program Manager
Division of Reactor Safety

Docket No. 50-440
License No. NPF-58

Enclosure: Inspection Report 50-440/2001014(DRS)
10 CFR 2.790(d) INFORMATION

cc w/encl: G. Tracy, NRR/DIPM/IOLB/RSS
B. Saunders, President - FENOC
N. Bonner, Director, Nuclear
Maintenance Department
G. Dunn, Manager, Regulatory Affairs
K. Ostrowski, Director, Nuclear
Services Department
T. Rausch, Director, Nuclear
Engineering Department
R. Schrauder, General Manager,
Nuclear Power Plant Department

cc w/encl w/o **10 CFR 2.790 INFORMATION**
A. Schriber, Chairman, Ohio Public
Utilities Commission
Ohio State Liaison Officer
R. Owen, Ohio Department of Health

ENCLOSURE CONTAINS 10 CFR 2.790 INFORMATION
UPON SEPARATION THIS PAGE IS DECONTROLLED

10 CFR 2.790(d) INFORMATION

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, excluding the enclosure, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/NRC/ADAMS/index.html (the Public Electronic Reading Room).

Sincerely,
/RA by James L. Belanger Acting for/
James R. Creed
Safeguards Program Manager
Division of Reactor Safety

Docket No. 50-440
License No. NPF-58

Enclosure: Inspection Report 50-440/2001014(DRS)
10 CFR 2.790(d) INFORMATION

cc w/encl: G. Tracy, NRR/DIPM/IOLB/RSS
B. Saunders, President - FENOC
N. Bonner, Director, Nuclear
Maintenance Department
G. Dunn, Manager, Regulatory Affairs
K. Ostrowski, Director, Nuclear
Services Department
T. Rausch, Director, Nuclear
Engineering Department
R. Schrauder, General Manager,
Nuclear Power Plant Department
cc w/encl w/o **10 CFR 2.790(d) INFORMATION**
A. Schriber, Chairman, Ohio Public
Utilities Commission
Ohio State Liaison Officer
R. Owen, Ohio Department of Health

DOCUMENT NAME: C:\MYFILES\Checkout\Per01-14DRS w-o10CFR2.790d ~.wpd
To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII		RIII		RIII			
NAME	GPirtle:jb		CLipa		JBelanger for JCreed			
DATE	10/26/01		10/26/01		10/29/01			

OFFICIAL RECORD COPY
ENCLOSURE CONTAINS 10CFR 2.790 INFORMATION
UPON SEPARATION THIS PAGE IS DECONTROLLED

10 CFR 2.790(d) INFORMATION

ADAMS Distribution w/encl
w/o **10 CFR 2.790(d) INFORMATION**:
AJM
DFT
DVP1
RidsNrrDipmIipb
GEG
HBC
CAL
C. Ariano
DRPIII
DRSIII
PLB1
JRK1

ENCLOSURE CONTAINS 10 CFR 2.790 INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED

10 CFR 2.790(d) INFORMATION

UPON SEPARATION THIS PAGE IS DECONTROLLED

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Docket No:	50-440
License No:	NPF-58
Report No:	50-440/01-14(DRS)
Licensee:	FirstEnergy Nuclear Operating Company (FENOC)
Facility:	Perry Nuclear Power Plant, Unit 1
Location:	P.O. Box 97 A200 Perry, OH 44081
Dates:	August 27 through 30, 2001
Inspector:	G. Pirtle, Physical Security Inspector
Approved by:	James R. Creed, Safeguards Program Manager Division of Reactor Safety

ENCLOSURE CONTAINS 10CFR 2.790 INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED

10 CFR 2.790(d) INFORMATION

SUMMARY OF FINDINGS

IR 05000440-01-14(DRS), on 08/27-30/2001; FirstEnergy Nuclear Operating Company, Perry Nuclear Power Plant. Physical Security Inspector Report.

The inspection was conducted by a region-based security inspector. The significance of most findings is indicated by their color (Green, White, Yellow, Red) using NRC Inspection Manual Chapter 0609 "Significance Determination Process" (SDP). The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described at its Reactor Oversight Process website at http://www.nrc.gov/NRR/OVERSIGHT/index.html.

A. Inspector Identified Findings

None

B. Licensee Identified Violation

A violation of very low significance which was identified by the licensee has been reviewed by the inspector. Corrective actions taken or planned by the licensee appear reasonable. This violation is listed in Section 4OA7 of this report.

ENCLOSURE CONTAINS 10CFR 2.790 INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED