DIAGRAMMATIC CROSS SECTION
SHOWING SUBSURFACE FAULTING AT BWIP

ENCLOSURE B



Council of Energy Resource Tribes

WORK COPY
SEPTEMBER 26, 1986
C.L. CANARD

TI APERTURE CARD

D01

8705180328-01