Hole at position 9-Right



Piece of master rod showing fracture surface



Fracture surface
Showing beach marks and "tiger stripes"



DG 22 Being Removed from its Bay at STP



DG22 arrives at EDC and is offloaded to repair shop floor.



DG22 Disassembly

Centerframe removal from base.



DG22 Repair

9R repair window complete and machined for door gasket.



DG22 Inspection

Rotor removed from generator to inspect stator



DG22 Reassembly

Cylinder liner preassembly in block