NRC FORM 591M PART 3
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE **United Technologies, Pratt&Whitney, East Hartford, CT** REPORT NUMBER(S) 2004-001	2. NRC/REGIONAL OFFICE **U.S. Nuclear Regulatory Commission** **Region I, 475 Allendale Road** **King of Prussia, Pennsylvania 19406-1415**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-03796	06-07522-02	3/4/2004

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87124	03.01-03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03120	5	Carlos Rivera, RSO	(860)557-2901

[X] Main Office Inspection — Next Inspection Date: Not Applicable

[ ] Field Office

[ ] Temporary Job Site

PROGRAM SCOPE

During this inspection, the licensee stated that the Gd-153 layer thickness gauge had been transferred from the East Hartford, CT facility to the licensee's facility in Berwick, Maine (an agreement state). The licensee stated that the necessary paper work for license termination would be submitted to NRC Region I.

No violations of safety concerns were identified.