VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

July 7, 1999

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No. 99-362
SS&L/BAG R0
Docket Nos. 50-281
License Nos. DPR-37

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 2
COMPLETION OF THERMO-LAG 330-1 CORRECTIVE ACTIONS

In a December 18, 1997 letter (Serial No. 97-697), Virginia Electric and Power Company committed to take specific corrective actions with regard to Thermo-Lag 330-1 radiant energy shields for Surry Power Station. These corrective actions were incorporated into Confirmatory Orders Modifying Licenses as a requirement for Surry Power Station on July 9, 1998. The corrective actions identified in the 1997 letter and the requirements of the Confirmatory Orders were completed during the last refueling outage for Surry Unit 2 which ended in May 1999. Virginia Electric and Power Company letter dated February 1, 1999 (Serial No. 99-011) documented the completion of these actions for Surry Unit 1.

If you have any further questions, please contact us.

Very truly yours,

E. S. Grecheck
Site Vice President

Commitments made in this letter:

1. None

1/0

A029

9907230340 990707
PDR ADOCK 05000281
P PDR

cc: U.S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth Street, SW
Suite 23T85
Atlanta, Georgia 30303

Mr. R. A. Musser
NRC Senior Resident Inspector
Surry Power Station