Docket 40-8943

From: "Michael Griffin" <griffin_cbr@earthlink.net>
To: "John H. Lusher" <jhl@nrc.gov>
Date: 5/14/04 6:38PM
Subject: Pond Leak Report

John:

Good day! How are you doing? Well, I hope.

I am writing to inform you of an apparent leak in the northwest quadrant of Pond 1. The underdrain level increased this week to above six inches. The sample that we obtained for conductivity was in excess of 50 percent of the conductivity of the pond contents, which is our action level for determining a pond leak. You may recall that the NW underdrain showed a leak in Pond 1 at this time last year. It is possible that the repair made at that time is leaking or that another leak was not found at that time.

We are setting up to transfer water from Pond 1 to Ponds 3 or 4 i order to allow us to identify the source of the leak. NDEQ was notified by phone today at 1250 MDT. I will keep you informed.

Take care.

Mike

Michael Griffin
Manager of Health, Safety, and Environmental Affairs
Crow Butte Resources, Inc.
PO Box 169
Crawford, Nebraska 69339

308.665.2215

griffin_cbr@earthlink.net

Mail Envelope Properties (40A89B2C.4FC : 18 : 22040)

Subject:	Fwd: Pond Leak Report
Creation Date:	5/17/04 6:59AM
From:	John Lusher
Created By:	jhl@nrc.gov

Recipients
twf4_po.TWFN_DO
BSG (Betty Garrett)

Post Office	**Route**
twf4_po.TWFN_DO	

Files	**Size**	**Date & Time**
Mail		
MESSAGE	571	05/17/04 06:59AM

Options

Expiration Date:	None
Priority:	Standard
Reply Requested:	No
Return Notification:	None
Concealed Subject:	No
Security:	Standard