#10

## Straka, Donald J(Z99942)

**From:** Kesler, Steven L(Z55768)
**Sent:** Wednesday, June 16, 2004 10:13 AM
**To:** Paramithas, Panos (V72983); Leake, Harvey C(Z60326)
**Cc:** Kesler, Steven L(Z55768); Phegley, Steven D(K74768)
**Subject:** Additional Digital Pictures of the Failed AR Relay

The pictures below show the nameplate and the contacts a little clearer. The location of the contacts makes it difficult to get a clear picture.
Steve K.

-----Original Message-----
**From:** Silva, Richard R(K85919)
**Sent:** Wednesday, June 16, 2004 9:27 AM
**To:** Kesler, Steven L(Z55768)
**Cc:** Phegley, Steven D(K74768)
**Subject:** Better photo of name plate

Liberty neplate.jpg (102 KB) Liberty Front View.jpg (94 KB)...

A/23


Westinghouse
STYLE 606B017A09A
125
VOLTS
DC
HERTZ
TYPE
AR
RELAY
INSTRUCTION LEAFLET
41-759