NRC FORM 591M PART 3
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
Quality Inspection and Testing, Inc REPORT NUMBER(S) 04-01	USNRC Region IV

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-32546	50-29038-01	December 17, 2004

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
IP87121	03.01-03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
3310	1	Chris Grass	907-479-4273

[X] Main Office Inspection — Next Inspection Date: 12/05

[ ] Field Office

[ ] Temporary Job Site

PROGRAM SCOPE

Small Industrial Radiography Licensee. President of company is Chris Grass who is also RSO and user. There is a second radiographer and 3 assistants. Licensee possesses 2 Spec 150 cameras. Usage is daily throughout the year in the Fairbanks area in addition to military bases. With exception of the 2 findings listed below all documentation relating to radiation safety and operation was in order. Last inspection was October 2003 and was clear. This inspection resulted in 2 SL 4 violations involving failures to: conduct a public dose assessment pursuant to 10 CFR 20.1301; and provide hazmat refresher training. Licensee was to perform the public dose assessment that day and will proceed to either download the HAZMAT modules from the DOT website or will obtain the training locally. The licensee agreed to accomplish these actions within 30 days. The violations and corrective actions were documented on a NRC form 591M form part 1 and a copy left on site.