NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
BRK Brands, Inc. 3901 Liberty Street Road Aurora, Illinois 60504 REPORT 2004-002, -003	REGION III US NUCLEAR REGULATORY COMMISSION 2443 WARRENVILLE ROAD, SUITE 210 LISLE, ILLINOIS 60532

3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION
030-32838	12-23809-01	Nov. 8 - Dec. 7, 2004

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☐ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

10 CFR 32.29 (c) requires, in part, that the licensee file a report with the Director of Nuclear Material Safety and Safeguards, U.S. NRC, regarding products transferred to other persons for use under 10 CFR 30.20 or equivalent regulations of an Agreement State within 30 days following five years after filing the previous report or filing an application for renewal of the license under 10 CFR 30.37. Contrary to the above, the licensee failed to file the above report within 30 days following the date that they filed for renewal of the license, July 22, 2002, and failed to file a report within the previous five years. Licensee will issue such a report within 30 days and will provide the required five-year report annually in order to ensure that the report is filed appropriately in the future.

34

JAN 31, 2005 (M) Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, ~~within 30 days~~, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	MARK DEVINE VINCENT B. MORI, SR. CORP. ENGR.	Mark Devine Vincent B. Mori	(M) 19 JAN 05
NRC INSPECTOR	Geoffrey M. Warren RADIATION SAFETY OFFICER	Geoffrey M. Warren	12/7/04