October 19, 2005

Mr. T.W. Hardgrove
Pathfinder Mines Corporation
935 Pendell Boulevard
P.O. Box 730
Mills, WY 82644

SUBJECT: ACKNOWLEDGMENT OF RECEIPT OF ANNUAL LAND USE SURVEY AND EFFLUENT REPORT, PATHFINDER MINES CORPORATION, LUCKY MC SITE, SOURCE MATERIALS LICENSE SUA-672 (TAC L60471)

Dear Mr. Hardgrove:

This letter is to acknowledge the receipt of the annual land use survey required per License Condition 21 and the effluent and environmental monitoring report per 10 CFR 40.65 and License Condition 22. U.S. Nuclear Regulatory Commission (USNRC) staff has reviewed the submittal and have no questions, at this time. It should be noted that the report cover letter dated August 30, 2005, indicated that no effluent and environmental monitoring were performed at the site per License Condition 64. If you have any questions, please contact me at 301-415-7182 or by e-mail at sjc7@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/NRC/reading-rm/adams.html.

Sincerely,

\RA\

Stephen J. Cohen, Project Manager
Uranium Processing Section
Fuel Cycle Facilities Branch
Division of Fuel Cycle Safety
and Safeguards
Office of Nuclear Material Safety
and Safeguards

Docket No.: 40-2259
License No.: SUA-672

October 19, 2005

Mr. T.W. Hardgrove
Pathfinder Mines Corporation
935 Pendell Boulevard
P.O. Box 730
Mills, WY 82644

SUBJECT: ACKNOWLEDGMENT OF RECEIPT OF ANNUAL LAND USE SURVEY AND EFFLUENT REPORT, PATHFINDER MINES CORPORATION, LUCKY MC SITE, SOURCE MATERIALS LICENSE SUA-672 (TAC L60471)

Dear Mr. Hardgrove:

This letter is to acknowledge the receipt of the annual land use survey required per License Condition 21 and the effluent and environmental monitoring report per 10 CFR 40.65 and License Condition 22. U.S. Nuclear Regulatory Commission (USNRC) staff has reviewed the submittal and have no questions, at this time. It should be noted that the report cover letter dated August 30, 2005, indicated that no effluent and environmental monitoring were performed at the site per License Condition 64. If you have any questions, please contact me at 301-415-7182 or by e-mail at sjc7@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/NRC/reading-rm/adams.html.

Sincerely,

\RA\

Stephen J. Cohen, Project Manager
Uranium Processing Section
Fuel Cycle Facilities Branch
Division of Fuel Cycle Safety
and Safeguards
Office of Nuclear Material Safety
and Safeguards

Docket No.: 40-2259
License No.: SUA-672

DISTRIBUTION:
FCFB r/f J. Whitten RIV

ML052870259

OFC	FCFB		FCFB		FCFB			
NAME	S. Cohen		B. Garrett		Acting Chief			
DATE	10/19/05		10/19/05		10/19/05			

OFFICIAL RECORD COPY