U.S. NUCLEAR REGULATORY COMMISSION

TELEPHONE CONVERSATION RECORD

Date: 11/29/2005

Time: 2:00 PM

Mail Control or Report No(s). 137670 License No(s). 29-00040-10 Docket No(s). 03011981

Name of Licensee:	Honeywell International, Inc
Name of Participant(s):	Alice Schussler
Telephone No.	732-968-9600
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	RAI, Discussion on Terminating License
Summary:	So that the license may be terminated, we need to get a statement of what areas had licensed material, what types of licensed materials were used, and the surveys which released those areas. Guidance is located in NUREG-1757, Volume 1, Revision 1. Review guidance for group 2 Decommissioning and simplified survey procedures in Figure 8.1. Additionally, leak tests results should be provided for all sealed sources within 6 months of transfer unless those leak tests have been submitted previously. The leak test of your last sealed source submitted was not within 6 months. This termination will require an environmental assessment which needs additional information. I will send another letter discussing the needed information.
Action Required:	Send a letter requesting additional information.

Document Availability: X Publicly Available ___ Non-Publicly Available

X Non-Sensitive ___ Non-Sensitive Copyright ___ Sensitive ___ Sensitive Copyright

X Immediate Release ___ Normal Release ___ Delay Release Date

Prepared & SISP Review Completed By: ***/ RA /*** Dennis Lawyer Date: 11/29/2005