Change Notice 05-033

	DELETED:		TRANSMITTED:	
	Number	Date	Number	Date
1.	IP 87132	10/24/02	IP 87132	12/06/05
2.	---------	----------	TI 0610/001	12/06/05

TRAINING: None.

REMARKS: IP 87132 (Brachytherapy Programs) has been revised [Section 03.01.b.2] in the first paragraph,"The inspector should review the method used by the licensee to confirm source homogeneity for sources used in the afterloading device. One acceptable method is autoradiography," was deleted to reflect the current regulations in 10 CFR 35.633.

TI 0610/001 (Guidance for Certain Fuel Cycle Inspection Reports to Pilot Use of NRC Form 591) is being issued to establish a pilot program to document inspections of fuel cycle facilities using the NRC Form 591.

DISTRIBUTION: Standard

END