INDUSTRIAL - ACADEMIC

Page 1 of ___

INSPECTION REPORT NO. 78-01

Attached
[ ] Appendix A
[ ] Appendix B
[ ] Appendix C
[ ] Memo

Department of the Army
U.S. Army Communications & Electronics Materials and Readiness Command
Ft. Monmouth, New Jersey

Licensee contact: Barry Silber Telephone no. 201-532-3493-4452

29-01022-42
License no. SMB-1300 Last amendment and date: 0 - 7/24/78, 2 - 8/8/78

Category: 6E2, and Priority: III, as of last amendment.

Inspection date(s): 10/20/78 Type of inspection: Routine, Unannounced.

SUMMARY OF FINDINGS AND ACTION

[X] No noncompliance, ~~o~~ Letter issued
[ ] Noncompliance, Appendix A
[ ] Action on previous noncompliance, Appendix B
[ ] Noncompliance, 591 issued
[ ] Regional action Hq action
[ ] Supplemental info, Appendix C

RECOMMENDATIONS

See basis in Appendix C or attached memo.

[X] Change Category of SMB-1300 to: E2-6
[ ] Change Priority to: ___
[ ] Next inspection date: 10/83

PERSONS CONTACTED

Barry Silber - Health Physicist.

E16

Inspector: [signature] 10/26/78

Approved: [signature] 11/6/78

Plan approved: _____ Date: _____

Licensee: _____ License no: _____

Inspection Items	Scheduled for inspection	Post-inspection status	Module no.	766 Time Info
Management meeting - Entrance and Exit Interviews [REQUIRED]	✓	Completed	30703B	10 min
Initial Management Meeting				
Program requirements, MC 2852 [REQUIRED]	✓	Completed	77710B	3/4 hr
Licensee Event Followup			92700B	
Followup on Inspector-identified problems			92701B	
Followup on Noncompliance and Deviations			92702B	
IE Bulletin/Immediate Action Letter Followup			92703B	
Followup on Headquarters Requests			92704B	
Followup on Regional Requests			92705B	
Independent Inspection Effort [REQUIRED]	✓	Completed	92706B	3/4 hr
Inspector Dispatched to Site			93700B	
Followup on Significant Event Occurring During Inspection			93701B	

29-01022-12 — This license is for material previously licensed under 6.C, 7.C, 8.C & 9.C of Lic. No 29-01022-08. Leak tests are no longer required for this equipment. This material is possessed and used by the Army throughout the world. The item has been replaced by a new model survey meter. The licensed model will be retained for some time by users who dont have a great deal of use for the instrument. The licensee maintains inventories of the item, and has been responsible for ordering and distributing it. It is now supervising disposal of replaced items.

SMB-1300 — None of these items have been received as yet. Within 2 months, 3 items will be received by another command for testing. When the item is received in various supply depots, it will be distributed and records maintain in the same manner as for the above item.