OPTIONAL FORM NO. 10
MAY 1962 EDITION
GSA GEN. REG. NO. 27

5010-107

UNITED STATES GOVERNMENT

Memorandum

TO : Files

THRU: P. R. Nelson, Senior Radiation Specialist
Region I, Division of Compliance

DATE: August 15, 1966

FROM : W. B. Grant, Radiation Specialist
Region I, Division of Compliance

SUBJECT: U. S. DEPARTMENT OF THE ARMY
WALTER REED ARMY MEDICAL CENTER
WASHINGTON, D. C.
LICENSE NUMBERS: 8-1738-2
SUB-603

Inspector Evaluation

The inspector's impression of the program as run by Holland and Lodde is generally excellent. Capt. Lodde who apparently does the bulk of the health physics work appears to be diligent, conscientious and well trained. In the opinion of the inspector, there are no health and safety problems associated with the licenses inspected and the program as set up indicates no problem in the foreseeable future.

License -1, Category G(I), recommend 6 month extension, inspect 1/68.

License SUB-603, Category G(IV), suggest 18 month extension, inspect 1/71.

2/3

Buy U.S. Savings Bonds Regularly on the Payroll Savings Plan

Form AEC-591
(6/1/65)

UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

6

1. LICENSEE	2. REGIONAL OFFICE
Department of the Army Walter Reed Army Medical Center Washington, D.C. 20012	U.S. Atomic Energy Commission Region I Division of Compliance 376 Hudson Street New York, N.Y. 10014
3. LICENSE NUMBER(S) SUB 603	**4. DATE OF INSPECTION** 19-20 July 1966 (Initial)

5. INSPECTION FINDINGS

See WRAMC file for details of inspection

- [X] A. No item of noncompliance was found.
- [ ] B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42
- [ ] C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42
- [ ] D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)
- [ ] E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
- [ ] F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)
- [ ] G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4)
- [ ] H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)
- [ ] I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)
- [ ] J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)
- [ ] K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)
- [ ] L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51
- [ ] M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)
- [ ] N. Records of inventories were not maintained. 10 CFR 34.26
- [ ] O. Utilization logs were not maintained. 10 CFR 34.27

W B Grant

(AEC Compliance Inspector)

6. LICENSEE'S ACKNOWLEDGMENT

The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.

(Date) *(Licensee Representative — Title or Position)*

COPIES: [ ] LICENSEE, [X] COMPLIANCE REGION, [X] DIV. OF ST. & LIC. REL., [ ] DIV. OF COMPLIANCE