SPECIAL LIMITED INSPECTION

1. Name and address of licensee
Union Carbide Corp.
Chemicals & Plastics Operations Div.
Tech Center
P.O. Box 8361
South Charleston, W.Va. 25303

2. Date of inspection
7/29/68

3. Type of inspection
R-3

4. License number(s), docket number(s), number and date of last amendment for each license. Category and Priority of each license
47-260-6
Thru Amend. No. 22 dtd Apr. 28, 1967
E, III

5. Date of previous inspection
6/3-4/65

6. Is "Company Confidential", or proprietory, or classified information contained in report?
Yes_____ No_____
(Specify paragraphs)

7. Scope of inspection
Special limited inspection conducted on the basis of memo from L.D. Low dtd April 3, 1968.

8. Inspector: [signature]
7/29/68
Date of Report

Reviewer: A.T. Sutherland
8/14/68
Date of Review

A-193

1 of 6

Bldg 770, 2nd floor, existing, Dr. Bricker
storage in hall of room 235
guardians in 237
both posted CRM symbol
both restricted areas - 24 hr. control by staff.
AEC-3 posted by entrance to room 237
surveys by Fred Willis d/or R.O. Mid Kff
release limiting limits
an inventory 5.0 mc. C-14
48.0 mc C-14
53.0 total
labeling CRM, isotope quantity, & date
Records of receipt maintained by Dr. Bricker from U Carbide
" of trans. to U Carbide
waste to Radiochemical Service Co. NJ
Labeled & only waste
C-14 — 61 mc
Ra 226 — 1.7 mc
Sr 90 — 20 mc
H-3 — .2 C
Cs 137 — 1 mc
Dr. Bricker authorized by Isotope committee (4/quarter)

2 of 6

N.C. Eastman, Project scientist
Bldg 770, 4th floor, room 458, tissue studies
85 mc C14 received from Union Carbide
85 mc C14 transferred to [illegible] Mellon Institute, Pittsburgh Pa.
liquid form
Inventory-none
Surveys by Fred Willis d/or R.O. Mid Kff
All work in hood (service 1200 cfm)
hood rubber gloves, no shielding
Sign CRM posted when required
Labeling CRM symbol ok, Also isotope quantity & date
No restricted area

Licensee Union Carbide Corp.

Summary

The use of Lic Mat. has not resulted in excessive external exposures or exposures to concentrations of radioactive materials. There has been no release of effluents to unrestricted areas. The radiation level in the unrestricted area has been less than 0.6 mr/hr.

Noncompliance and Safety Items

None (clear)

Unusual Occurrences

No loss
No overexposures
No malfunctions
No ingestion
No inhalation
No spills

(None)

Status of Previously Reported Noncompliance or Safety Items

N/A (clear)

Management Interview

The inspection findings were discussed with Mr. R. M. Berg Asst. Director of R & D. Dept.

Tech center for Group 1 of Union Carbide
Group 1 consists of chemical & Plastics production facilities of Union Carbide



Isotopes Committee
Mr. N.H. Ketcham – chairman, South Charleston Plant
Mr. C.G. Corvic, South Charleston Plant
Mr. V.O. Foglesong, Institute Plant
Mr. D.L. Heywood, R&D Dept, Tech Center
Mr. B.L. Murray, South Charleston Plant
Mr. R.E. Peele, Institute Plant
Mr. C.E. Pownall, Purchasing
Mr. R.V. Seeley, Engineering Dept
Mr. Fred. Williams, RSO, Tech Center

Meets on infrequent basis. Last met formally 1 Oct 20, 1965. Minutes kept should there be a Health or Safety problem. it would be brought to the attention of committee.

Licensee Union Carbide Corp

Mr. N. Landfried, Inst. Engineer

Mr. H.L. Green, Inst. Engineer
Mr. R.V. Sealey, Group Leader
Dr. D.L. Kaylwood, Group Leader
Mr. T. Kennell, Project chemist
Mr. Ray Louther, chemist

DETAILS

A. Participants

Mr. N.H. Ketcher, Chairman - Isotopes Committee, RSO for - 6 license
Dr. J.H. Bricker, Project scientist
Mr. R.G. Tyndall, Asst RSO for -4 and part of -6 Lic
Mr. N.C. Eastman, Project scientist
Mr. J.K. Rose, Group Leader

B. Scope of License Program

Tracer studies associated with chemical industry (study of chemical reactions)

C. Organization

Mr. Ketcher - RSO for -6 license & Experience at K-25 plant ORNL. 4 years exp. at ORNL plus 17 years exp at Union Carbide
Mr. Fred Williams - RSO for -4 licenses & Experience at Y-12 Plant ORNL. 12 years exp. at ORNL plus 5 years exp. at Union Carbide

organization (see back of page 2)
Isotopes Committee " " " "
Ketcher approves all non encapsulated sources
Williams " " " encapsulated sources

D. Administrative Control

Authorized quantities of isotopes received
Authorized users selected by Isotopes Committee

E. Use of Material

Tracer studies associated with R&D in the chemical field

Inventory

C-14 - 53 mc + 68 mc + 50.11 mc = 103.178 mc
Cl-36 - 20 μc
S-35 - 19.37 mc
H-3 - 100.0 mc

3 of 6

Bldg 770 4th floor, room 4226
J.K. Rose Group Leader (chemist)
Ray Gauthier, chemist
Lab tech

C-14 - 68 MC
storage is locked cabinet -
William & Midkiff survey
rubberglove, paper label
receipt from Univ Calif
trans. to Phillip-Morris, Richmond
& Univ Florida

Labeling ok
Posting on cabinet ok
No restricted area
work in hood

4 of 6

Bldg 770 1st floor, room 158
Mr. T Kennell, project chemist
None on survey

From Tweedle 20 mc
" : Undisclosed 45 mc
To: 112 mc disposed to Radiological Services TLG
To: 15 mc to limited storage
To 8 mc " " "
Survey by Fred Willis & Ro. Midkiff (air & wipe sigstaff)
No pitting, use rubberglove, absorbent pigs
All is closed system
Lab is locked in Adm, in hallway
Labeling ok
Area posted CRL symbol ok
work in hood

Licensee: Union Carbide Corp.

F. Facilities

Same as reported by Ellis in report of inspection on June 3-4, 1965

G. Equipment

Same as reported by Ellis in report of inspection on June 3-4 1965

H. Radiological Safety Procedures

Manual for use of Radioactive Materials (see folder) followed as required.

I. Personnel Monitoring and Exposure to External Radiation

No PD or FD. Their use evaluated & determined that PD & FB would serve no useful purpose.

J. Exposure of Employees to Concentrations of Radioactive Materials

None

5 of 6 Lab 324 Bldg 740

Dr. D.L. Heywood Greg Leslie

Transitions in Agriculture study

C-14, Cl-36, S-35, H-3 (Solids)

MAC synthesis

From:- NEN, Volk, Mallinckrodt, Union Carbide

To:; Mellon Inst., Union Carbide, Texas A&M.

U of Calif (Riverside & Berkeley); US Dept of Agr. Beltsville, MD & Fargo, N.D.

(2 inc.)

Enclosed synthesis

Surveys - Fred Williams, 8 yrs. Y-12 (HP at Ind. Hyg.), 9 yrs. here

Accident, injection

Shipping

C-14 - 50.11 mc S-35 - 19.37 mc

Cl-36 - 20 MC H-3 - 100 mc

Storage

Lab 4 refrigerator - samples

(6 of 6)

R.V. Sealey Org Leader M.L. Grecheck Instr. Tech. Bldg 740 Lab 324 Mr. M Landfried, Ill. Tech. Eng.

Ilt. gray (Sealed sources) Tracer Work

Cs 137
Cs 131
Xe 85
Zr 133
} ORNL Union Carbide

No inventory

Disposal by Radiological Services

Savings by F. Williams

C-14 — 1.9 mc

Bldg 745

Inst Lab - storage of C-14 Ill. Tech.

ORNL Sign

AEC-3

Licensee Union Carbide Corp.

K. Effluents to Unrestricted Areas

calculations of effluents show all fume hood releases to be less than Pt 20 limits

L. Disposals

All disposals to Radiological Services Inc., NJ.
Records maintained
one Since last inspection, 2/7/67, C-14, 61 mc; Ra 226, 1.7 mc
Sr 90, 20 mc; Cs 137, 1 mc; tHz, 12 C.

M. Miscellaneous Surveys, Evaluations, and Records

Mr. Fred Williams surveys all areas during periods of work
Records maintained. No evidence of contamination & no
radiation levels greater than 0.6 mr/hr.

N. Special License Conditions

No incineration
No sealed sources therefore no leak testing

O. Posting and Labeling

All work & storage areas posted CRT with TL symbol
All containers labeled " " " Also isotope quantity
All restricted areas posted For AEC-5, as required

Licensee Union Carbide Corp.

P. Independent Measurements

Eberline E 500-B.
Survey of Lab. - No evidence of contamination on floor work benches & sinks
No radiation levels greater than 0.6 mr/hr.

Q. Operations Observed

None

R. Incidents, Overexposures, Theft or Loss, Equipment Malfunction

None

S. Other Information or Continuation from Previous Paragraphs

None