
REGION R16
ERPA(s) to be Evacuated
1
2
3
4
5
6
7
8
9
10
11
12
13
Scottsboro
Hollywood
Pisgah
Dutton
Section
Sylvania
Henagar
Langston
Powell
Rainsville
Pleasant Groves
Skyline
Stevenson
Hytop
Ider
N
S
E
W
0 1 2 3 4 5
Miles