TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

June 12, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNIT 1 - SURFACE CRACKS IN LOOP ONE STEAM GENERATOR - NCR 1844R - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector B. J. Cochran on October 23, 1979, in accordance with 10 CFR 50.55(e). Interim reports were submitted on November 23, 1979, January 22, 1980, and April 9, 1980.

Westinghouse has proposed a corrective action to the problem of the surface indications. TVA is reviewing the Westinghouse corrective action and pursuing appropriate action to prevent recurrence. We will submit our next report by September 9, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/0

8006190385

An Equal Opportunity Employer