From: Steven West R3
To: James Caldwell
Date: 08/07/2007 2:38:20 PM
Subject: Follow up to issues we discussed this morning

1. Davis-Besse circ water line leak. Licensee will weld a temporary patch over the pipe crack and will replace the pipe section during the next outage (Jan 2008). We are still reviewing the repair plan. Repair could be completed within the next few days.

2. Palisades tracer gas leak. This incident did not adversely impact the control room or the operators. While testing the HEPA filter between the mechanical equipment room and the control room, the hose from the tracer test gas tank to the filter became disconnected and released the gas into the mechanical equipment room. The NLOs left the room and allowed the gas to dissipate through an open door. No gas was released into the control room. The three NLOs, and 2 security guards who entered the room shortly after the gas release, were taken by the licensee to a local doctor for evaluation.

3. DFI order. Jared sent you an e-mail that provided the latest on the confirmatory order. Looks like everything is in place to

CC: Mark Satorius

F-68

Mail Envelope Properties (46B8CA2C.BF5 : 10 : 4022)

Subject: Follow up to issues we discussed this morning
Creation Date 08/07/2007 2:38:20 PM
From: Steven West

Created By: KSW@nrc.gov

Recipients
nrc.gov
ch_po.CH_DO
JLC1 (James Caldwell)
MAS CC (Mark Satorius)

Post Office	**Route**
ch_po.CH_DO	nrc.gov

Files	**Size**	**Date & Time**
MESSAGE	1397	08/07/2007 2:38:20 PM

Options

Expiration Date:	None
Priority:	Standard
ReplyRequested:	No
Return Notification:	None
Concealed Subject:	No
Security:	Standard

Junk Mail Handling Evaluation Results
Message is not eligible for Junk Mail handling
Message is from an internal sender

Junk Mail settings when this message was delivered
Junk Mail handling disabled by User
Junk Mail handling disabled by Administrator
Junk List is not enabled
Junk Mail using personal address books is not enabled
Block List is not enabled