Change Notice 08-019

| DELETED: | | | TRANSMITTED: | |
| --- | --- | --- | --- | --- |
| Number | Date | | Number | Date |
| 1. IP 71004 | 05/09/06 | | IP 71004 | 07/01/08 |
| 2. IMC 0801 | 10/19/06 | | IMC 0801 | 07/01/08 |
| 3. _____ | _____ | | IP 65001.15 | 07/01/08 |
| 4. _____ | _____ | | IP 73054 | 07/01/08 |
| 5. _____ | _____ | | IP 80522 | 07/01/08 |
| 6. _____ | _____ | | IP 84527 | 07/01/08 |

TRAINING:  None

REMARKS:  IP 71004 (Power Uprate) has been revised to address concerns identified during the OIG 2007 audit of the Power Uprate process by providing guidance on planning, tracking, and documenting completion of IP 71004. In addition, previously provided guidance was moved to Section 02, "Inspection Requirements and Guidance," and referenced baseline procedures were changed to reflect the 2007 ROP realignment.

IMC 0801 (Reactor Oversight Process Feedback Program) has been revised to more efficiently use Technical Assignment Control (TAC) numbers for management of the feedback process.

IP 65001.15 (Inspection of ITAAC-Related Installation of Fire Protection Equipment) is issued to support Inspections, Tests, Analyses, and Acceptance Criteria (ITAAC)-related new reactor construction inspections under 10 CFR Part 52.

IP 73054 (Part 52, Preservice and Inservice Inspection - Review of Program) is issued to support inspections of operational programs

described in IMC 2504, "Construction Inspection Program - Non-ITAAC Inspections."

IP 80522 (Part 52, Radiological Environmental Monitoring Program (REMP) is issued to support inspections of operational programs described in IMC 2504, "Construction Inspection Program - Non-ITAAC Inspections."

IP 84527 (Part 52, Solid Waste Management System) is issued to support inspections of operational programs described in IMC 2504, "Construction Inspection Program - Non-ITAAC Inspections."


DISTRIBUTION:  Standard


END