NRC FORM 591M PART 1
(10-2003) 10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
City of Owosso 301 W. Main Street Owosso, MI 48867	**U.S. Nuclear Regulatory Commission** **Region III** **2443 Warrenville Road** **Suite 210** **Lisle, Illinois 60532-4351**
REPORT NUMBER(S) 2008-001	

3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION
030-28983	21-18888-03	July 10, 2008

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☒ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura	Deborah A. Piskura	7/10/2008

NRC FORM 591M PART 3
(10-2003) 10 CFR 2.201

Docket File Information

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
City of Owosso REPORT NUMBER(S) 2008-001	**Region III** **2443 Warrenville Road, Suite 210** **Lisle, IL 60532**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-30130	21-18888-03	July 10, 2008

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87124	03.01 – 03.08

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03121	5	Ronald Baker, RSO	517-723-8844

[X] Main Office Inspection — Next Inspection Date: July 2013

[ ] Field Office

[ ] Temporary Job Site Inspection

PROGRAM SCOPE

The licensee was small municipal office employing 100 individuals. The licensee possessed one moisture/density gauge used occasionally for road testing projects during the construction season. The licensee approved 2 individuals (both successfully completed the manufacturer's training course) as authorized gauge users. The licensee did not perform any service or maintenance activities on its gauge; these services were performed by the device manufacturer.

During this inspection, the inspector toured the gauge storage area, surveyed the gauge storage room, interviewed selected licensee personnel, and reviewed selected records. Licensee personnel discussed and demonstrated security measures in the field, transportation procedures and emergency procedures. At the time of this inspection the gauge was not in use. Therefore, the inspector was unable to conduct a field inspection.