

NOTES:

1. ALL PIPING TO BE Q.A. TYPE "IC" UNLESS OTHERWISE NOTED .
2. THIS DWG. TO BE WORKED WITH PHYSICAL PIPING DWG. NF-39797-4

REVISIONS
0
DRAWN BY: JLB DATE: 2-27-07 PREPARED BY: RAB DATE: 2-27-07 REVIEWED BY: SRM DATE: 2-27-07
1
REVISED (a)(1) BOUNDARY DRAWN BY: JLB DATE: 7-31-07 PREPARED BY: WJI DATE: 7-31-07 REVIEWED BY: SRM DATE: 8-1-07

LR - LEGEND

- IN SCOPE FOR LR PER 10 CFR 54.4(a)(1) 10 CFR 54.4(a)(3)
- IN SCOPE FOR LR PER 10 CFR 54.4(a)(2)
- OUT OF SCOPE
- DENOTES SYSTEM BOUNDARY BREAK

CHANNEL №: 1-R-30 & 1-R-37
INSTRUMENT №: 29004 & 29049

LR - SYSTEMS

RD - RADIATION MONITORING
ZA - AUX. AND RADWASTE AREA VENTILATION

D-084

INTERLOCK LOGIC DIAGRAM NF-40750

RADIATION MONITORING SYS. INSTRUMENT FLOW DIAGRAM CHANNELS 1-R-30 & 1-R-37 AUXILIARY BUILDING VENT GAS MONITORS "B" & "A"

REFERENCE DWG. NE-39790-9 REV. C

SIG No.	8630				4400	1	3400
GROUP	1	2	3	4	5	QL	9

PRAIRIE ISLAND NUCLEAR GENERATING PLANT LR-39790 SHEET 9 REV. 1

This map / document is a tool to assist employees in the performance of their jobs. Your personal safety is provided for by using safetypractices,procedures and equipment as described in safety training programs, manuals and SPAR's.

$$USERNAME$$
$$$$$$SYTIME$$$$$$$$$$$$SYDATE$$$$$$
$$$$$$$$$DESIGNFIL$$$$$$$$$

LR-39790-9.DGN [NSP GENERATION CAD]