

REFER TO SPECS :

XH-02400-66 (ERECTION)
XH-02400-79 (SUPPORTS)
XH-02400-80 (MATERIAL)
XH-02400-81 (VALVES)

LEGEND:

- ---·--- DENOTES SACM MANUFACTURERS STANDARDS.
- SR DENOTES SAFETY RELATED ASME III
- NON-SR DENOTES NON-SAFETY RELATED ANSI B31.1
- ◈ DENOTES VALVES AND INSTRUMENTS FURNISHED WITH EQUIPMENT BY SACM PER LR-XH-02610. (MANUFACTURERS STANDARDS).
- ---·--- INSTRUMENTATION BOUNDED BY AND ENCLOSED BY THIS LINE REPRESENTS SACM SUPPLIED INSTRUMENTATION.

NOTES:

NUCLEAR SAFETY RELATED ITEMS ARE SHOWN ON THIS DRAWING.

REFERENCE DWG. NF-118251 REV. B

D-107

This map / document is a tool to assist employees in the performance of their jobs. Your personal safety is provided for by using safety practices, procedures and equipment as described in safety training programs, manuals and SPAR's.

DWN	DATE	SIGNIFICANT NO.	8630		410	2	4410	1	8300
CHECKED		GROUP	1	2	3	4	5	CL	6
PROJECT NO.									
APP'D & CERT.									
FILMED									

LICENSE RENEWAL BOUNDARY DWG
DIESEL GENERATOR D6
STARTING AIR FLOW DIAGRAM UNIT 2

NORTHERN STATES POWER COMPANY
Xcel Energy
PRAIRIE ISLAND NUCLEAR GENERATING PLANT
RED WING, MINNESOTA

SCALE NONE | REV 1

LR-118251

$$USERNAME$$ $$$$$$SYSTIME$$$$$$$$$$SYDATE$$$$$$ $$$$$$$$$$DESIGNFILE$$$$$$$$$$

LR-118251.DGN NSP GENERATION CAD