BellefonteRAIsPEm Resource

From: Brian Anderson
Sent: Monday, July 21, 2008 3:17 PM
To: BellefonteRAIsPEm Resource
Subject: REQUEST FOR ADDITIONAL INFORMATION LETTER NO. 084 RELATED TO SRP SECTION 09.01.04 FOR THE BELLEFONTE UNITS 3 and 4 COMBINED LICENSE APPLICATION
Attachments: BLN-RAI-LTR-084.doc

Importance: High

Hearing Identifier: Bellefonte_COL_RAI_Public
Email Number: 62

Mail Envelope Properties (CB87FC66F95637428C5E0D066E756B6F7C72EA8249)

Subject: REQUEST FOR ADDITIONAL INFORMATION LETTER NO. 084 RELATED TO SRP SECTION 09.01.04 FOR THE BELLEFONTE UNITS 3 and 4 COMBINED LICENSE APPLICATION
Sent Date: 7/21/2008 3:17:20 PM
Received Date: 7/21/2008 3:17:21 PM
From: Brian Anderson

Created By: Brian.Anderson@nrc.gov

Recipients:
"BellefonteRAIsPEm Resource" <BellefonteRAIsPEm.Resource@nrc.gov>
Tracking Status: None

Post Office: HQCLSTR01.nrc.gov

Files	**Size**	**Date & Time**
MESSAGE	3	7/21/2008 3:17:21 PM
BLN-RAI-LTR-084.doc	53754	

Options
Priority: High
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

July 21, 2008

Ms. Andrea L. Sterdis
Manager, Nuclear Licensing & Industry Affairs
Nuclear Generation Development & Construction
Tennessee Valley Authority
1101 Market Street
Chattanooga, Tennessee 37402-2801

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION LETTER NO. 084 RELATED TO SRP SECTION 09.01.04 FOR THE BELLEFONTE UNITS 3 and 4 COMBINED LICENSE APPLICATION

Dear Ms. Sterdis:

By letter dated October 30, 2007, as supplemented by letters dated November 2, 2007, January 8, 2008 and January 14, 2008, Tennessee Valley Authority (TVA) submitted its application to the U. S. Nuclear Regulatory Commission (NRC) for a combined license (COL) for two AP1000 advance passive pressurized water reactors pursuant to 10 CFR Part 52. The NRC staff is performing a detailed review of this application to enable the staff to reach a conclusion on the safety of the proposed application.

The NRC staff has identified that additional information is needed to continue portions of the review. The staff's request for additional information (RAI) is contained in the enclosure to this letter.

To support the review schedule, you are requested to respond within 45 days of the date of this letter. If changes are needed to the final safety analysis report, the staff requests that the RAI response include the proposed wording changes.

If you have any questions or comments concerning this matter, you may contact me at 301-415-9967 or you may contact Joesph Sebrosky, the lead project manager for the Bellefonte combined license at 301-415-1132.

Sincerely,

/**RA**/

Brian C. Anderson, Project Manager
AP1000 Projects Branch 1
Division of New Reactor Licensing
Office of New Reactors

Docket Nos. 52-014
52-015

Enclosure:
Request for Additional Information

CC: see next page

If you have any questions or comments concerning this matter, you may contact me at 301-415-9967 or you may contact Joesph Sebrosky, the lead project manager for the Bellefonte combined license at 301-415-1132.

Sincerely,

/**RA**/

Brian C. Anderson, Project Manager
AP1000 Projects Branch 1
Division of New Reactor Licensing
Office of New Reactors

Docket Nos. 52-014
52-015
eRAI Tracking No. 290

Enclosure:
Request for Additional Information

Distribution:

Public	SCoffin	SLee
RidsNroDnrlNwe1	TSimms	GPurciarello
RidsNroLAKGoldstein	RJoshi	
RidsOgcMailCenter	BHughes	
RidsAcrsAcnwMailCenter	MComar	
RidsRgn2MailCenter	AHodgdon	
JSebrosky	PMoulding	

NRO-002

OFFICE	COLP/BC		NWE1/PM	OGC	NWE1/L-PM
NAME	PWilson*		TSimms*	AHodgdon*	JSebrosky*
DATE	5/9/08		6/6/08	6/29/08	7/21/08

*Approval captured electronically in the electronic RAI system.

OFFICIAL RECORD COPY

Request for Additional Information
Bellefonte Units 3 and 4
Tennessee Valley Authority
Docket No. 52-014 and 52-015
SRP Section: 09.01.04 - Light Load Handling System (Related to Refueling)
Application Section: 9.1.4

QUESTION from Balance of Plant Branch 2

09.01.04-1

RAI-9.1.4-SBPB-01 AP1000 DCD Revision 16 Section 9.1.6.5, “Inservice Inspection Light Load Handling System,” states that the COL applicant is responsible for a program for inservice inspection of the light load handling system as specified in Section 9.1.4.4 of the DCD Revision 16. This is identified as COL Information Item 9.1-5. In Section 9.1.4.4 of the Bellefonte COLA, the applicant has responded to this COL information item by stating “STD COL 9.1-5 The above requirements are part of the plant inspection program for the light load handling system, which is implemented through procedures. In addition to the above inspections, the procedures reflect the manufacturer’s recommendations for inspection.” Please verify that these procedures are established as stated in the COL information item (in the DCD Revision16) and STD COL 9.1-5 (in the COLA) and are currently available for NRC inspection or provide the schedule in relation to fuel loading for issuance of the procedures and describe how this action will be tracked to ensure completion of the COL information item.