NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201 — U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Northern Virginia Radiology & Nuclear Medicine, Inc. 8320 Old Courthouse Road, Suite 150 Vienna, Virginia 22182 REPORT Nos 2007-001	U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-03327	45-08482-01	12/18/07 & 5/20/08 (phone)

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☐ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 71.5(a) and requires, in part, that a licensee who delivers licensed material to a carrier for transport comply with the applicable requirements of the regulations of the Department of Transportation (DOT) in 49 CFR Parts 170-189. Also, 49 CFR 172.702 requires, in part, that each Hazmat Employer shall ensure that each Hazmat Employee is trained and tested, and that no Hazmat Employee perform any function subject to the requirements of 49 CFR Parts 171-177 unless trained, in accordance with Subpart H of 49 CFR Part 172. Contrary to the above, as of January 5, 2008, the licensee had not provided training to its Hazmat Employees as required by Subpart H to 49 CFR Part 172.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Peter PARAS Ph.D.		06/10/2008
NRC INSPECTOR	Willie J. Lee		06/05/2008

NRC FORM 591M PART 1 (Rev. by RI 07/08) G:\Docs\Current\Insp Record\R45-08482-01.2007-001.Part1.wpd

SUNSI Review Completed By: /RA/ Willie J. Lee ☒ Public ☒ Non-Sensitive