TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

April 18, 1985

WBRD-50-391/85-12 85 APR 22 A11 : 37

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - HYDROGEN COLLECTOR PIPING COULD BE OVERSTRESSED - WBRD-50-391/85-12 - SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector D. M. Verrelli on February 14, 1985 in accordance with 10 CFR 50.55(e) as NCR WBN MEB 8506. Our final report was submitted on March 19, 1985. Below is our supplemental final.

As discussed with NRC-OIE Inspector S. Weise on April 8, 1985, the date of April 8, 1985 for completion of corrective actions indicated in our final report on this matter was not met. More extensive modifications to the unit 2 piping were required than anticipated based on the unit 1 modifications. The corrective action on this matter will be completed by July 31, 1985.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham
J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8505280120 850418
PDR ADOCK 05000391
S PDR

IE 27

An Equal Opportunity Employer