TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA
81 DEC 3 A8:3

December 2, 1981

WBRD-50-390/81-40
WBRD-50-391/81-39

RECEIVED
DEC 7 1981
U.S. NUCLEAR REGULATORY COMMISSION

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - VALVE MODELING ERROR - WBRD-50-390/81-40, WBRD-50-391/81-39 - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on April 10, 1981 in accordance with 10 CFR 50.55(e) as NCR CEB 8106. Interim reports were submitted on May 11, August 18, and September 23, 1981. We expect to provide additional information by March 3, 1982. TVA is still in the process of reanalyzing the piping problem using the correct valve modeling.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

for L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

IE 27 s/o

8112070403 811202
PDR ADOCK 05000390
S PDR