TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

US. REGION II
ATLANTA, GEORGIA

December 11, 1981

DEC 15 A8:34

WBRD-50-390/81-09
WBRD-50-391/81-08

RECEIVED
DEC 17 1981
US NUCLEAR REGULATORY COMMISSION
DOCUMENT MANAGEMENT BR
TIDC

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - HIGH DENSITY SPENT FUEL RACKS - WBRD-50-390/81-09, WBRD-50-391/81-08 - SUPPLEMENTAL INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on December 17, 1980, in accordance with 10 CFR 50.55(e) as NCR WBN CEB 8012. TVA considers 10 CFR Part 21 to be applicable to this deficiency. TVA's final report on this deficiency was submitted on June 18, 1981.

In that final report, TVA committed to formally revise Watts Bar Quality Control Procedure (QCP) 4.22 by June 30, 1981. This commitment was not met. However, as discussed with Inspector R. V. Crlenjak on November 25, 1981, the revision to the QCP was issued on August 14, 1981.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

for L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8112180420 811211
PDR ADOCK 05000390
S PDR

OFFICIAL COPY

I 2.27