TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA
81 DEC 11 A9:00

December 9, 1981

WBRD-50-390/81-33
WBRD-50-391/81-32
WBRD-50-390/81-50
WBRD-50-391/81-48

DEC 17 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPER CLASSIFICATION OF ERCW SYSTEM PIPING AND COMPONENTS - WBRD-50-390/81-33, WBRD-50-391/81-32, WBRD-50-390/81-50, WBRD-50-391/81-48 - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on March 24, 1981 in accordance with 10 CFR 50.55(e) as NCR WBN NEB 8106. A similar deficiency was initially reported to NRC-OIE Inspetor R. V. Crlenjak on May 7, 1981 in accordance with 10 CFR 50.55(e) as NCR 3116R1. Interim reports were submitted on April 24, June 8, July 14, and September 2, 1981. TVA is continuing to evaluate this nonconformance. We expect to submit our next report by February 4, 1982.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
s
1/0

8112180439 811209
PDR ADOCK 05000390
S PDR

An Equal Opportunity Employer