TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

December 29, 1981

WBRD-50-390/81-36
WBRD-50-391/81-35

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - ANCHOR BOLTS INSTALLED NOT IN ACCORDANCE WITH SPACING SPECIFICATIONS - WBRD-50-390/81-36, WBRD-50-391/81-35

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on March 31, 1981, in accordance with 10 CFR 50.55(e) as NCR SWP 8106. Interim reports were submitted on April 30, May 21, June 4, September 16, and December 2, 1981. Our last three reports (third, fourth, and fifth interims) stated that TVA considers 10 CFR Part 21 applicable to this deficiency. However, as discussed with Inspector R. V. Crlenjak on December 3, 1981, the reference to 10 CFR Part 21 was inadvertent and will be deleted in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

JAN 5 1982

8201060505 811229
PDR ADOCK 05000390
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 27