TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

82 MAY 25 A11:12

May 20, 1982

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly,
Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAULTY FILLET WELDS - NCR 2111R - REVISED TENTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on February 20, 1980 in accordance with 10 CFR 50.55(e) in conjunction with similar deficiencies designated as NCR's 2006R, 2091R, 2101R, 2120R, 2128R, 2137R, and 2375R. Interim reports were submitted on March 19, May 6, August 8, and October 31, 1980 and February 6, June 17, October 13, and December 31, 1981 and February 25 and April 28, 1982.

In our last interim report we erroneously stated that our next report would be submitted by May 4, 1982. As discussed with Inspector R. V. Crlenjak on May 18, 1982, TVA expects to provide its next report on this deficiency by May 4, 1983.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8206010287
S

OFFICIAL COPY

IE 27
S-110

An Equal Opportunity Employer