TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA
82 MAY 28 A8:2

May 25, 1982

WBRD-50-390/81-92, -391/81-26
BLRD-50-438/81-69, -439/81-68
HTRD-50-518/81-27, -519/81-21
-520/81-26, -521/81-22
PBRD-50-553/81-30, -554/81-23
YCRD-50-566/81-23, -567/81-19

U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR, BELLEFONTE, HARTSVILLE, PHIPPS BEND, AND YELLOW CREEK - REPORTABLE DEFICIENCY - RECEIVING, CHECKING, AND CONTROLLING RECORDS -WBRD-50-390/81-92, -391/81-26 - BLRD-50-438/81-69, -439/81-68 - HTRD-50-518/81-27, -519/81-21, -520/81-26, -521/81-22 -PBRD-50-553/81-30, -554/81-23 - YCRD-50-566/81-23, -567/81-19

The subject deficiency was initially reported to P. A. Taylor on October 27, 1981 as NCR M81-0 Deficiency No. 2. The final report was submitted on February 8, 1982. As discussed with Ross Butcher on May 11, 1982, TVA was unable to meet the May 3, 1982 commitment date for completion of corrective actions. TVA now anticipates completing corrective actions on or before July 30, 1982.
If you have any questions, please call Jim Domer at FTS 858-2725 for BWRs or Ralph Shell at FTS 858-2676 for PWRs.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

D S Kammer

for L. M. Mills, Manager
Nuclear Licensing

cc: Mr. R. C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

T222

8206070104 820525
PDR ADOCK 05000390
S PDR