WATTS BAR NUCLEAR PLANT

TECHNICAL INSTRUCTION

TI-50A

ASME SECTION XI
PRESERVICE INSPECTION PROGRAM

Unit 1

Rev. By	Rev. No.	Date	Revised Pages
N/A	0	7/14/81	All
JLC	1	9/29/81	Page 55
JLC	2	10/2/81	Page 103

The last page of this instruction is number 136.

1C	Plant Master File
1C	Superintendent
1C	Assistant Superintendent
1C	Mechanical Maintenance Supervisor
1C	Results Supervisor
1C	Operations Supervisor
1C	Quality Assurance Supervisor
1C	Health Physicist
	Administrative Supervisor
2C	Chemical Laboratory
1C	Instrument Shop
	Shift Engineer's Office
	Unit Control Room
	Health Physics Laboratory
1C	PSU Supervisor
1C	Mechanical Engineer
	Reactor Engineer
	Chemical Engineer
1C	Instrument Maintenance Supervisor
1C	Asst. Director of Nuc Power (Oper)
1C	Electrical Maintenance Supervisor
1C	Outage Director
1U	NRC
1C	Nuclear Safety Review Staff
1C	Assistant Maintenance Supervisor
1U	Supv. Reactor Systems Group
1U	Plant Training Office
1C	P Prod Training Center
2C	Unit Control Room
1C	Codes & Standards Group
1C	Baseline Inservice Inspection Group

Prepared By G. L. Belew

Submitted By J. R. Collins
Supervisor

PORC Review 7/14/81
Date

Approved By [signature]
Superintendent

Date Approved for 7/14/81

8111240693 811118
PDR ADOCK 05000390
S PDR



WBNP
TI-50A
APPENDIX A
PAGE 54 OF 60
REVISION 2