TIC

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

NRC REGION II
ATLANTA, GEORGIA
81 MAY 8 A7:30

May 6, 1981

RECEIVED
MAY 14 1981
U.S. NUCLEAR REGULATORY COMMISSION

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-21 - RII:JPO 50-328, -390, -391, -438, -439, -566, AND -567 - SEQUOYAH UNIT 2, WATTS BAR, BELLEFONTE, AND YELLOW CREEK NUCLEAR PLANTS - RESPONSE TO BULLETIN

In response to your letter dated November 6, 1980, which transmitted IE Bulletin 80-21 on valve yokes supplied by Malcolm Foundry Company, Inc., we have completed the required review. We have determined that no valves or valve parts made by Malcolm Foundry Company, Inc., are used or planned for use in safety-related systems at Sequoyah unit 2, Watts Bar, Bellefonte, or Yellow Creek Nuclear Plants.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Division of Reactor Construction
Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8105190138

Q

An Equal Opportunity Employer