81-446-000
Part 21

400 Chestnut Street Tower II

June 4, 1981

WBRD-50-391/81-24

RECEIVED
JUN 09 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNIT 2 - LACK OF WESTINGHOUSE QUALITY ASSURANCE REVIEW ON FIELD CHANGE NOTICE - WBRD-50-391/81-24 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on February 27, 1981, in accordance with 10 CFR 50.55(e) as NCR WBN NEB 8103. TVA considers this deficiency to be potentially reportable under 10 CFR 21. Our first interim report was submitted on April 3, 1981. We expect to provide additional information by August 5, 1981.

TVA is evaluating this problem with Westinghouse. Westinghouse has inspected the subject valve discs at the site to the same requirements as on unit 1 and has issued a quality release. The final report will include information describing the steps taken to prevent recurrence.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE19
S1/0

8106100274
3

IE19