TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
500 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA
82 JUL 6 A9:10

July 2, 1982

WBRD-50-390/82-63
WBRD-50-391/82-60

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - SPENT FUEL POOL GATES - WBRD-50-390/82-63, WBRD-50-391/82-60 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Don Quick on June 1, 1982 in accordance with 10 CFR 50.55(e) as NCR WBN NEB 8005. Enclosed is our first interim report. We expect to submit our next report by November 1, 1982. This deficiency has also been reported on the Bellefonte Nuclear Plant as NCR BLN NEB 8005.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

D S Kammer

for L. M. Mills, Manager
Nuclear Licensing

Enclosure
cc: Mr. Richard C. DeYoung, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8207090239 820702
PDR ADOCK 05000390
S PDR

OFFICIAL COPY
IE 27

ENCLOSURE

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2
SPENT FUEL POOL GATES
NCR WBN NEB 8005
WBRD-50-390/82-63, WBRD-50-391/82-60
10 CFR 50.55(e)
FIRST INTERIM REPORT

Description of Deficiency

The spent fuel pool gates (one to the transfer canal and one to the cask loading area) are not designed to seismic requirements in accordance with Regulatory Guide 1.13.

Interim Progress

This matter is being evaluated, and we will provide additional information in the next report.