TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

86 APR 16 A11 : 18

April 11, 1986

WBRD-50-390/83-56

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 1 - PRESSURIZER LEVEL TRANSMITTERS DO NOT COVER PROCESS RANGE - WBRD-50-390/83-56 - SUPPLEMENTAL FINAL REPORT FOR UNIT 2

The subject deficiency was initially reported to NRC-OIE Inspector Linda Watson on August 29, 1983 in accordance with 10 CFR 50.55(e) as NCR W-138-P. Our last report on this item was submitted on January 9, 1984. This constitutes our supplemental final report for unit 2.

As discussed with Bob Carroll on February 27, 1986, the date of March 1, 1986 for completion of the corrective actions indicated in our final report was not met. While the unit 2 transmitters have been returned to the site with the corrected range and have been installed, work has not been completed on installation of the sensor bellows nor has necessary calibration and testing been completed. This work will be completed before unit 2 fuel load.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8604230382 860411
PDR ADOCK 05000390
S PDR

1/0 IE27