TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

April 11, 1986

WBRD-50-391/82-71

U.S. Nuclear Regulatory Commission
Region II
Attention: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - POSTACCIDENT READINGS FROM CONTAINMENT SUMP LEVEL TRANSMITTERS - WBRD-50-391/82-71 - THIRD SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on July 8, 1982 in accordance with 10 CFR 50.55(e) as NCR WBN SWP 8236. Our last report on this item was submitted on November 8, 1983. This constitutes our third supplemental report.

As discussed with Bob Carroll on January 21, 1986, the date of January 15, 1986 for completion of the corrective actions indicated in our final report was not met. Due to the administrative hold on instrumentation work, the changeout of fill fluid for the unit 2 transmitters has been delayed. This will be completed before unit 2 fuel load.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

for R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8604230389 860411
PDR ADOCK 05000391
S PDR

1/0 IE27