TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

86 APR 16 A11:18

April 11, 1986

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - STEAM GENERATOR WATER LEVEL REFERENCE COLUMN ERROR - NCR MEB 79-33 - SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. Thomas on July 6, 1979 in accordance with 10 CFR 50.55(e) as NCR MEB 79-33. Our last report was submitted on May 6, 1985. This constitutes our supplemental final report.

As discussed with Gordon Hunegs on March 19, 1986, the date of March 6, 1986 for completion of the corrective actions indicated in our final report was not met. The steam generator insulation cannot be installed until the instrument sense lines are installed. The sense line installation has been delayed by the administrative hold on instrumentation work. The corrective action for this deficiency will be complete before unit 2 fuel loading.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8604240441 860411
PDR ADOCK 05000390
S PDR

1/0 IE27