TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
5N 157B Lookout Place

May 6, 1986

WBRD-50-390/83-66
WBRD-50-391/83-61

U.S. Nuclear Regulatory Commission
Region II
Attention: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAILURE TO PROVIDE SELF-CONTAINED LIGHTS AS COMMITTED TO NRC - WBRD-50-390/83-66, WBRD-50-391/83-61 - SECOND SUPPLEMENTAL FINAL REPORT FOR UNIT 2

The subject deficiency was initially reported to NRC-Region II Inspector Linda Watson on November 9, 1983 in accordance with 10 CFR 50.55(e) as NCR WBN MEB 8305. Our last report on this item was submitted on January 30, 1985. This constitutes our second supplemental final report for unit 2.

As discussed with Gordon Hunegs on April 21, 1986, the date of April 10, 1986 for completion of the corrective actions indicated in our final report was not met. Because of changes in the unit 2 construction schedule, the installation of unit 2 lights had to be rescheduled. The corrective action for this matter will be complete by unit 2 fuel load.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. L. Gridley

R. L. Gridley, Director
Nuclear Safety and Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8605210458 860505
PDR ADOCK 05000390
S PDR

1/0 IE27