TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
5N 157B Lookout Place

86 MAY 12 P1:47

May 8, 1986

WBRD-50-390/86-21
WBRD-50-391/86-17

U.S. Nuclear Regulatory Commission
Region II
Attention: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAILURE TO IDENTIFY A RECURRING PROBLEM WITH A SIGNIFICANT NCR - WBRD-50-390/86-21, WBRD-50-391/86-17 - SCHEDULE CHANGE FOR NEXT REPORT

The subject deficiency was initially reported to NRC-Region II Inspector Al Ignatonis on January 6, 1986 in accordance with 10 CFR 50.55(e) as audit deficiency WB-S-86-019-D01. Our interim report on this item was submitted on February 20, 1986.

As discussed with Gordon Hunegs on May 5, 1986, the next report for this deficiency will be provided by July 2, 1986 rather than May 16, 1986. This delay is required due to the reorganization of the sections responsible for developing and implementing actions to prevent recurrence of the deficiency.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. L. Gridley, Director
Nuclear Safety and Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8605210465 860508
PDR ADOCK 05000390
S PDR

1/0 IE 27