CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/18/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: Get shipments - start QC	Task 2: GWS
Task 3:	Task 4:
Task 5:	Task 6:
Training Requirements:	

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[X]No;RWP # _____ Confined Space [ ] Yes[X]No; # _____

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: Cold, slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.): GWS

Types of Communications: Cell phone

Special Topics:

Lessons Learned from Previous Day: Stay warm

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	Joe McGinley		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Joe McGinley	Joe McGinley	Cabrera
Derrick Albert	Derrick Albert	Cabrera
Greg Bright	[illegible]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/19/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Continue QC instruments	Task 2: Set up GWS equipment
Task 3: Start GWS	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.): N/A

Physical Hazards: Cold, slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.): N/A

PPE: N/ level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications: Cell phone

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	Joe McGinley		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Joseph McGinley		Cabrera
Derrick Albert		Cabrera
Greg Bright		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/20/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: GWS	Task 2: Sample locations
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work?	[✓] Yes	[ ] No
Permits Required: RWP [ ]Yes[X]No;RWP # _____	Confined Space [ ] Yes[X]No; # _____	

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: cold, slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications: cell phone

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	Joe McGinley	[illegible]	Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
Derrick Albert	[illegible]	Cabrera
Joe McGinley	[illegible]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/23/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: GWS	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: cold, slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications: Cell phone

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	Joe McGinley	[illegible]	Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
Derrick Albert	Derrick Albert	Cabrera
Joe McGinley	[illegible]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/24/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: GWS	Task 2: Soil sampling
Task 3: —	Task 4: —
Task 5: —	Task 6: —

Training Requirements: Rad worker, Hazwaper

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # N/A Confined Space [ ] Yes[✓]No; #

Radiation Hazards: Very low soil contamination. Dose rates ~10-20 μRem/hr

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: STF,

Work Control Methods (JHA, Work Plan, monitroing, etc.): WP

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.): GWS

Types of Communications: Cell phones.

Special Topics: don't fall in test pits. Watch out for wildlife.

Lessons Learned from Previous Day: watch GWS. Cold weather advisory. Stay Warm!!

Questions & Feedback from Attendees: None.

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Joe Weismann		Cabrera
Safety and Health Rep.:	Joe McGinley		Cabrera

MEETING ATTENDEES

Print Name	Signature	Company
Greg Bright		Cabrera
Derrick Albert		Cabrera
DAVE KATELEY		"
JIM WEISMANN		"
Joe McGinley		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/26/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Soil sampling	Task 2: GNS
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: Slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[signature]	Cabrera
Radiolgical Lead:	Joe Weismann		Cabrera
Safety and Health Rep.:	Dave Katelley		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[signature]	Cabrera
Joe Weismann	[signature]	Cabrera
DAVE KATELEY	[signature]	CABRERA

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/27/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Sampling in warehouses	Task 2: Shipping samples
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [ ] No

Permits Required: RWP [ ]Yes[ ]No;RWP # _____ Confined Space [ ] Yes[X]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards:
SLIPS, TRIPS + FALLS,

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: LEVEL "D"

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONES \ LINE OF SIGHT

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	Dave Kateley		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
DAVE KATELEY	[illegible]	CABRERA

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/30/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: Soil sampling	Task 2: GWS
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: cold, slips, trips, falls

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	Dave Kutelley		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright		Cabrera
DAVE KUTELEY		"

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/31/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Indoor Sampling	Task 2: Sample shipping
Task 3: Soil sampling	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards:

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	DAVE KADELEY	[illegible]	"

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
DAVE KADELEY	[illegible]	"

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/1/06
General Scope of Work: Characterization of Residual Radioactivity Throughout Site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: SAMPLE REF AREA 1	Task 2: BIAS SAMPLING
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:
H

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
DARK AREAS IN WAREHOUSES, SLIP, TRIPS + FALLS.
TRUCK TRAFFIC

Work Control Methods (JHA, Work Plan, monitroing, etc.):
RAD MONITORS

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):
NONE

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	DAVE KATELEY	D. [illegible]	CABRERA

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
DAVE KATELEY	D. [illegible]	CABRERA
Greg Bright	[illegible]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/2/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Outdoor Surveys	Task 2: Bldg 210 investigation
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards: Ceiling tiles in 210 - wear hardhats

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	DAVE KATELEY	D.	"

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright		Cabrera
DAVE KATELEY	Dave K	CABRERA

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/6/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Warehouse Surveys	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards: Slips, trips, falls, COLD

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	Greg Bright		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright		Cabrera
Bill Gardner		Cabrera
IVN HARRIS		Cabrera
Derrick Albert		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: D6-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 10/7/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: INSIDE BUILDING SURVEYS	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ] Yes [✓] No; RWP # _____ Confined Space [ ] Yes [✓] No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards:
WET SURFACES - SLIPS, TRIPS + FALLS.
PINCH POINTS - TRUCK TRAFFIC

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):
SICCORS LIFT

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	DAVE KATELEY		"

MEETING ATTENDEES		
Print Name	Signature	Company
DAVE KATELEY		CABRERA
Ian Harris		Cabrera
Jerrick Albert		Cabrera
Greg Bright		Cabrera
Bill Gardner		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/8/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: SURVEY WALLS B-24,212,213	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:
40 hr HAZWOPER + 8hr REFRESHER, RAD WORKER TRNG.

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [✓] Yes [ ] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards: N/A

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
SLIP, TRIP + FALLS, DARKENED WORK AREA, TRUCK TRAFFIC

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:
Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[signature]	Cabrera
Radiolgical Lead:	Greg Bright	[signature]	Cabrera
Safety and Health Rep.:	DAVE KATELEY	D. K[signature]	CABRERA.

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
DAVE KATELEY	D. K[signature]	CABRERA
Derrick Albert	D. Albert	CABRERA
Ian Harris	[signature]	cabrera
Bill Gardner	B. Gardner	Cabrera
Greg Bright	[signature]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/9/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: SURVEY WALLS B-210 + 213	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ] Yes [✓] No; RWP # _____ Confined Space [ ] Yes [✓] No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
TRUCK TRAFFIC - SLIPS, TRIPS + FALLS.

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	DAVE KATELEY	DK	CABRERA

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
DAVE KATELEY		CABRERA
Bill Gardner		Cabrera
Greg Bright		Cabrera
Ian Harris		Cabrera
Derrick Albert		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/13/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers		
Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):	
Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks	
Task 1: SURVEY RAFTERS + FLOORS	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:
40 hr HAZWOPER, 8 hr REFRESHER, RAD WORKER TRNG.

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ] Yes [✓] No; RWP # _____ Confined Space [ ] Yes [✓] No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
SLIPS, TRIPS + FALL, SCISSORS LIFT,

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):
MAN LIFT

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	DAVE KAIZELEY		CABRERA

MEETING ATTENDEES		
Print Name	Signature	Company
DAVE KAIZELEY	D.	CABRERA.
Greg Bright		Cabrera
Ian Harris		Cabrera
Nicholas Berliner		Cabrera
Bill Gardner		Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/14/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: Floor Scans in warehouse	Task 2: Wall Scans in 136
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ] Yes [✓] No; RWP # _____ Confined Space [ ] Yes [✓] No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
SLIP, TRIP + FALL, DARK WORK AREAS
TRUCK TRAFFIC

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONE

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	DAVE KATELEY	[illegible]	CABRERA

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
DAVE KATELEY	[illegible]	"
Bill Gardner	[illegible]	Cabrera
Nicholas Berliner	[illegible]	Cabrera
Ian Harris	[illegible]	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/15/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone #:
Name:	Phone #:
Name:	Phone #:

Days Work Tasks

Task 1: FLOOR SURVEYS WAREHOUSES	Task 2:
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:
40 hr HAZWOPER, 8 hr REFRESHER, RAD WORKER TRNG

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work? [ ] Yes [✓] No

Permits Required: RWP [ ]Yes[✓]No;RWP # _____ Confined Space [ ] Yes[✓]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):
NONE

Physical Hazards:
COLD WEATHER, SLIPS TRIP + FALL, TRUCK TRAFFIC

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE: Level D

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:
CELL PHONES

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	DAVE KATELEY	D.	"

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
DAVE KATELEY	D.	CABRERA
Greg Bright		Cabrera
Bill Gardner		Cabrera
Ian Harris		cabrera
Nicholas Berliner	Nicholas	Cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/20/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: Count smears	Task 2: Ship materials
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work?	[ ] Yes	[ ] No
Permits Required: RWP [ ]Yes[ ]No;RWP # _____	Confined Space [ ] Yes[ ]No; # _____	

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards:

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE:

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright		Cabrera
Radiolgical Lead:	Greg Bright		Cabrera
Safety and Health Rep.:	Ian Harris		Cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright		Cabrera
Ian Harris		cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

DAILY SAFETY TOOLBOX MEETING

Project Name: New Haven Characterization	Project #: 06-3070.02 20
Location: New Haven Depot New Haven, IN	Date/Time: 11/21/06
General Scope of Work: Characterization of Residual Radioactivity Throughout site	

Emergency Telephone Numbers

Police: 911	Fire: 911	Ambulance: 911

Other (UXO, Facility, etc.):

Name:	Phone # :
Name:	Phone # :
Name:	Phone # :

Days Work Tasks

Task 1: Count smears	Task 2: Pick up
Task 3:	Task 4:
Task 5:	Task 6:

Training Requirements:

SAFETY AND HEALTH INFORMATION

Job Safety Analysis completed for this work?	[ ] Yes	[ ] No

Permits Required: RWP [ ]Yes[ ]No;RWP # _____ Confined Space [ ] Yes[ ]No; # _____

Radiation Hazards:

Chemical Hazards (Incld marking paint, deconagents, etc.):

Physical Hazards:

Work Control Methods (JHA, Work Plan, monitroing, etc.):

PPE:

Special Equipment (Generators, backhoes, ISOCS, etc.):

Types of Communications:

Special Topics:

Lessons Learned from Previous Day:

Questions & Feedback from Attendees:

Meeting Conducted by	Print Name	Sign Name	Company
Cabrera Field Lead:	Greg Bright	[illegible]	Cabrera
Radiolgical Lead:	Greg Bright	[illegible]	Cabrera
Safety and Health Rep.:	Ian Harris	[illegible]	cabrera

MEETING ATTENDEES		
Print Name	**Signature**	**Company**
Greg Bright	[illegible]	Cabrera
Ian Harris	[illegible]	cabrera

Signature indicates that the employee understands the content of the breifing, has been given the opportunity to ask questions, provide feedback or raise concerns, and has completed the specified training requirements.

2/14/2002