Generalized Stress Provinces
FIGURE 2.5.1-209

Rev 0

COMANCHE PEAK NUCLEAR POWER PLANT
UNITS 3 AND 4