

(Reference 269)

FIGURE 2.5-243b
TVA Dam Safety Seismic Hazard Analysis Seismotectonic Source Zones